



GROUNDLOGS

Client: Big Company
Project: Ed's Gas Station
Address: 123 Main Street, Anytown, State

BORING LOG
Boring No. SB-1
Page: 1 of 1

Drilling Start Date: 1/2/2018	Boring Depth (ft): 19
Drilling End Date: 1/2/2018	Boring Diameter (in): 8.25
Drilling Company: Drilling Co.	Sampling Method(s): Grab, SPT, Core
Drilling Method: Hollow Stem Auger	DTW During Drilling (ft): 6.3
Drilling Equipment: Mobile B-61	DTW After Drilling (ft): 5.8
Driller: John Smith	Ground Surface Elev. (ft): 20.0
Logged By: Bill Logger	Location (X,Y): 44.5137053, -64.2973644

DEPTH (ft)	LITHOLOGY	WATER LEVEL	BORING COMPLETION	COLLECT				SOIL/ROCK VISUAL DESCRIPTION	MEASURE		DEPTH (ft)
				Sample Type	Date & Time	Blow Counts	Recovery (ft)		PID (ppm)	Lab Sample	
0				GR	08:00 1/2		1.0	(0') ASPHALT.			0
1.5				SS	08:15 1/2	2 2 3	1.5	(0.5') Poorly graded GRAVEL with sand (GP); mostly coarse grained gravel, some medium-coarse sand, loose, dry, light gray (SUBBASE). (1') Silty SAND (SM); mostly fine-medium grained sand, trace fine gravel, little silt, trace clay, poorly graded, loose, moist, light brown.	2.1		
5				SS	08:30 1/2	5 6 7	0.5	(5') Becomes medium dense, with hydrocarbon odor. (6') Becomes wet.	8.4	SB-1d6	5
10				SS	08:45 1/2	6 7 7	1.0	(10') Lean CLAY (CL); few fine gravel, trace coarse sand, little silt, mostly clay, medium plasticity, stiff, moist, dark brown.	0.2	SB-1d12	10
15				SS	09:00 1/2	8 8 9	1.5	(15') Silty SAND (SM); mostly fine-medium grained sand, trace fine gravel, little silt, trace clay, medium dense, saturated, light brown.	0.0		15
17.5				CO	09:15 1/2		1.5	(17.5') SED ROCK (SANDSTONE); medium sand, moderately bedded, slightly weathered, moderately hard, very slightly fractured, light reddish-brown, moist.			
19								(19') Boring terminated.			20

NOTES: Hole pre-cleared to 5' on 1/1/2018 08:00 by Borehole Clear Co. using Hand Auger.